



Jacobsen Service Bulletin

Product Type: Model 4300

Ref. No. N/A

Bulletin No: C-031-05

July 25, 2005

4300 Throttle Cable

Action Required

ISSUE:

We have received reports from the field that Throttle Plates are bending on Kohler Engines.

CORRECTION:

When replacing Throttle Cable 47-135 on a 4300 you will need to order Throttle Cable 4138319. Install the cable in the hole below current hole and use an existing clamp on the engine.

PARTS INVOLVED:

47-135
4138319

INVOLVED PRODUCTS:

73-70005, 73700050101 up to and including 73700050137

WARRANTY:

You may claim up to 0.2 hours of labor for units covered under this bulletin. Please file warranty using Service Bulletin Number C-031-05 with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 option 2,3,1.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

