

# Jacobsen Service Bulletin

Product Type: Mid-Size

Ref. No. N/A

Bulletin No: C-038-05

August 8, 2005

## Throttle Cable

### Action Required

#### ISSUE:

We have received reports of the throttle cable coming in contact with the muffler and melting the plastic coating.

#### CORRECTION:

When replacing throttle cable part number 38357-04 you will need to replace it with part number **38357-09** on the listed models below.

#### PARTS INVOLVED:

38357-04

38357-09

#### INVOLVED PRODUCTS:

732010A, 733010A and 734010A

#### WARRANTY:

You may claim up to 0.2 hours of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number **C-038-05** with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 option 2,3,1.

## CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☒

PARTS

☒