

Jacobsen Service Bulletin

Product Type: 4300 Tractor

Ref. No. **002**

Bulletin No: **C-149-03**

September 2003

Idler Bracket Arm

ISSUE:

Incorrect Idler Arm may be missing a gusset, causing arm to bend under load.
Lift Bracket may not have a tapered leading edge welded on the right-hand side making installation difficult.

CORRECTION:

Please replace Idler Arm and Lift Bracket.

AFFECTED SERIAL NUMBERS

73-70005 serial numbers 73700050101 up to and including 73700050111

73-70006 serial numbers 73700060101 up to and including 73700060108

73-70008 serial numbers 73700080101 up to and including 73700080107 excluding 73700080106

PARTS INVOLVED:

62-760.7 Idler slider bracket arm

62-833.7 Lift Bracket

WARRANTY:

You may claim parts and 1.5 hours labor allowed for tractors covered under this bulletin. Please file warranty in the normal manner with one tractor per claim and include service bulletin number on the warranty claim when filing.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☒