



Bulletin No: SB2005-10

Category: Steiner

Section: N/A

Index Ref: N/A

**Machine/s: Model 430
75-70005**

Pages: 1

Date: July 25,2005

Type: Product Information

TO: All Steiner Dealers

SUBJECT: 430 Throttle Cable

ISSUE:

We have received reports from the field that Throttle Plates are bending on Kohler Engines.

CORRECTION:

When replacing Throttle Cable 47-135 on a 430 you will need to order Throttle Cable 4138319. Install new cable in the hole below the current hole and use an existing clamp that is on the engine.

AFFECTED SERIAL NUMBERS:

75-70005, 75700050101 up to and including 75700050580

WARRANTY:

You may claim up to 0.2 hours of labor for units covered under this bulletin. Please file warranty using Service Bulletin Number SB2005-10 with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 select option 2,3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☒

PARTS

☒

