

Bobcat/Bunton Information Bulletin

Product Type: **LEO/ESTATE PRO**

Ref. No.

Bulletin No: **C-154-03**

October 2003

Transmission Maintenance

Product Information

ISSUE:

LEO: Correction to manual 4125725 and 4125725 Rev. A and 4125725 Rev. B.

ESTATE PRO: Correction to manual 4125721 and 4125721 Rev. A and 4125721 Rev. B. **We DO NOT require you to change the transmission hydraulic oil after 5 hours of use as stated in the Maintenance Record section of the manual.**

CORRECTION:

On the page labeled Maintenance Record of the Bob-Cat/Bunton Operation, Safety and Maintenance Manual, you need to change the NOTE on the bottom of the page to read as follows: **After first 5 hours of operation replace engine oil and filter.** This is for LEO/ESTATE PRO models only.

INVOLVED PRODUCTS:

All serial numbers for the following models:

LEO: 942280, 942281 and 942282

ESTATE PRO: 642280, 642281 and 642282

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒

