

Bobcat / Bunton Information Bulletin

Product Type: ZT2 Series/ BZT2 Series

Ref. No.

Bulletin No: C-156-03

October 2003

Pump Idler Upgrade Kit 970299

Product Information

ISSUE:

If the pump idler or idler mounting pin needs to be replaced please service with ZT2/BZT2 Series Pump Idler Upgrade Kit 970299.

CORRECTION:

Service pump idler assemblies with kit 970299 for below listed units.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:

ZT2: 942200, 942201, 942202, 942203, 942206, 942207, 942208
942209, 942212, 942213, 942215, 942211, 942220, 942221
942222, 942223, 942224, 942225, 942226, 942227, 942228,
942230, 942231, 942232, 942233, 942234, 942235, 942236
942211A, 942212A, 942220A 942221A, 942222A, 942223A
942224A, 942227A, 942228A, 942230A, 942231A, 942233A
942237A 942238A, 942239A

BZT2: 642201, 642203, 642204, 642206, 642207, 642211,
642213, 642215, 642220, 642221, 642222, 642223,
642225, 642226, 642227, 642228, 642230, 642231,
642233 642234, 642235, 642211A, 642212A, 642220A,
642221A, 642222A, 642223A, 642227A, 642228A,
642230A, 642231A, 642233A, 642237A, 642238A, 642239A

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒