



Product Type: BZT3310 Ref. No. 004

Bunt on

Service Bulletin J473

May 2000

Caster Supports

Models Affected: 642300

Issue

We have received reports from the field that under certain applications the Caster Support Arms **2256002.7** and **2256003.7** may be cracking.

Correction

If your Caster Support Arms are cracking around the mounting holes please order the following parts:

(1) **2256002.7** Caster Support RH, (1) **2256003.7** Caster Support LH, (4) **64123-24** Bolts, (4) **64229-05** Nuts, and (8) **64163-67** Washers.

Effective Serial Number

All 642300 units.

Warranty

Please file warranty in the normal way with only one unit per claim. You may claim for parts and up to 15 minutes labor (each side) for units in the normal warranty period.

Parts Involved

2256002.7 Caster Support RH.
2256003.7 Caster Support LH.
64123-24 Bolts.
64229-05 Nuts.
64163-67 Washers.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.