



Bobcat/Bunton Service Bulletin

Product Type: ZT2 / BZT2

Ref. No. N/A

Bulletin No: C-028-04

July 22, 2004

Electric Clutch Jumper Harness

Action Required

ISSUE:

We are receiving reports that there is voltage spikes that can damage the EFI controller on the units equipped with a 28HP Kohler engine.

CORRECTION:

The clutch jumper harness needs to be replaced with part number 4135344.

PARTS INVOLVED:

2720949-clutch jumper harness (Old)

4135344-jumper diode harness (New)

INVOLVED PRODUCTS:

642238A serial numbers 64223800101 up to and including 00111

642239A serial numbers 64223900101 up to and including 00132

942238A serial numbers 94223800101 up to and including 00149

942239A serial numbers 94223900070, 00101 up to and including 00163

WARRANTY:

You may claim parts and up to 20 minutes of labor allowed for units covered under this bulletin. Please file warranty, using **Factory Approval Number C-028-04**, with one unit per claim. If you have any questions please contact the Johnson Creek Customer Service Team at 1-800-848-1636 option 2,2.

All repairs must be completed by December 22, 2004. No warranty claims for this repair will be processed after January 22, 2005.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☒