



Bulletin No: SB2003-02
Category: Speciality Product
Section: Steiner - Brouwer
Index Ref: N/A
Machine/s: 415 & 430 Tractors
Pages: 1
Date: July 2003

Type: Technical Product Information

TO: All Steiner Dealers

SUBJECT: PTO Belt Length

Action Required

ISSUE:

PTO belt (STEINER 5L420) may be incorrect in length. The incorrect belt will carry the 5L420 part number but not the STEINER logo. The correct belt must carry the STEINER LOGO.

CORRECTION:

Install correct PTO belt. The correct belt must carry the STEINER LOGO.

EFFECTIVE SERIAL NUMBERS:

75-70005 serial numbers - 75700050101 up to and including 75700050150

75-70006 serial number - 75700060103

75-70008 serial numbers - 75700080101 up to and including 75700080108

75-60010 serial numbers - 75600100101 up to and including 75600100121

WARRANTY:

You may claim parts and up to 1 hour of labor for tractors covered under this bulletin. Please file warranty in the normal manner with one tractor per claim.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒