





Bulletin No: SB2003-04 Category: STEINER

Section: Index Ref: N/A

Machine/s: 415/430 Tractors

Pages: 1

Date: September 2003

Type: ACTION REQUIRED

TO: All Steiner Dealers

SUBJECT: 62-760.7 Idler Slider Bracket Arm

62-833.7 Lift Bracket

ISSUE:

Idler Arm may be missing a gusset, causing arm to bend under load. Lift_Bracket may not have a tapered leading edge welded on the right-hand side making installation difficult.

CORRECTION:

Please replace Idler Arm and Lift Bracket.

AFFECTED SERIAL NUMBERS:

75-60010 serial number 75600100070

75-60010 serial numbers 75600100101 up to and including 75600100127

75-70005 serial number 75700050070

75-70005 serial number 75700050101 up to and including 75700050165

75-70006 serial number 75700060070

75-70006 serial numbers 75700060101 up to and including 75700060106

75-70008 serial number 75700080070

75-70008 serial numbers 75700080101 up to and including 75700080114 excluding

75700080107, 75700080111 and 75700080112

WARRANTY:

You may claim parts and 1.5 hours labor allowed for tractors covered under this bulletin. Please file warranty in the normal manner with one tractor per claim and include service bulletin number on the warranty claim when filing.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. I	Please circulate as	appropriate
---	---------------------	-------------

SERVICE X WARRANTY X SALES PARTS X

