



Bulletin No: SB2003-05
Category: STEINER
Section:
Index Ref: N/A
Machine/s: 17.5 B&S Engine
Pages: 1
Date: September 2003

Type: ACTION REQUIRED

TO: All Steiner Dealers
SUBJECT: 17.5 Briggs & Stratton Engine

ISSUE:

Units may have been shipped without choke-a-matic stop screw removed or missing linkage.

CORRECTION:

Check to see if the stop screw is installed, if the stop screw is installed please remove and discard it. If the choke link is not installed on engine, call the Johnson Creek Customer Service Department at 1-800-848-1636 option 2, 2. They will send you the choke link and instructions you need to do the repair.

AFFECTED SERIAL NUMBERS:

44228000101-00113

WARRANTY:

You may claim up to .5 hours for adding the linkage. Please file the claims with one unit per claim.



CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒