



**Bulletin No: SB2004-09**

**Category: STEINER**

**Section: N/A**

**Index Ref: N/A**

**Machine/s: Model 230**

**Pages: 1**

**Date: September 10, 2004**

**Type: Product Information**

**TO: All Steiner Dealers**

**SUBJECT: Drive shaft**

**ISSUE:**

We have received reports of the drive shaft failing on the 230's with the Kubota Diesel engines.

**CORRECTION:**

When replacing the drive shaft you will need to order part number 4131504. This will have the improved shaft and Hayes coupler.

**AFFECTED SERIAL NUMBERS:**

75-70260 serial numbers FC3036 up to and including FC3913

75-70260 serial numbers FNC3008 up to and including FNC3632

75-70265 serial numbers RC3914 up to and including RC4583

75-70265 serial numbers 757026500070 up to and including 757026500147

**WARRANTY:**

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen product support team at 1-800-848-1636 option 3,2.

**CustomerOne™ Product Support**

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☐ SALES ☐ PARTS ☒