



Bulletin No: SB2004-10

Category: STEINER

Section: N/A

Index Ref: N/A

Machine/s: Model 230

Pages: 1

Date: November 1, 2004

Type: Product Information

TO: All Steiner Dealers


SUBJECT: Drive Axle Seal

ISSUE:

Oil leaking from inside axle seal on shaft part number 51-024.

CORRECTION:

Install a seal part number 4134039, behind axle bearing (see diagram).



AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:

Model 75-70254

Model 75-70256

Model 75-70258

Model 75-70265

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☒