



Bulletin No: SB2005-08
Category: Steiner
Section: N/A
Index Ref: N/A
Machine/s: Model 230 (75-70265)
Pages: 1
Date: May 23, 2005

Type: Product Bulletin

TO: All Steiner Dealers

SUBJECT: Engine Ground Cable

ISSUE:

Battery ground cable and Engine ground strap may be improperly installed.

CORRECTION:

Remove engine ground strap with star washer from the lower engine mounting plate. Reinstall the ground strap with the star washer to a direct frame bolt. It is necessary to remove the paint under this bolt to insure a proper ground. Check all other grounding points for paint removal or star washers.

AFFECTED SERIAL NUMBERS:

75-70265

75702650150 up to and including 75702650211.

WARRANTY:

You may claim up to 20 minutes labor for units covered under this bulletin. Please file warranty, using **Campaign Number SB2005-08** with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team at 1-800-8481636 option 2,3.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☐

