



*One BOB-CAT Lane
P.O. Box 469
Johnson Creek, WI 53038-0469*

*Phone: 920.699.2000
Fax: 920.699.2657*

Product Type: STEINER 430

Bulletin No: JC-020-07

August 30, 2007

Service Bulletin

Action Required

Installing a heat shield in the 430-33G

ISSUE:

Complaints of heat circulating under the dash causing the controls to get hot

CORRECTION:

Install a heat shield between the engine and dash

PARTS INVOLVED: See diagram next page

(1)	4163039.7	Heat Shield
(2.97 FT)	56-068	Trim
(2)	64139-04	Bolt
(2)	64141-2	Nut

PRODUCTS INVOLVED:

75-70010A

WARRANTY:

You may claim up to 1/2 hour of labor and parts for units covered under this bulletin.
Please file warranty using Service Bulletin Number CGC-020-07 with one unit per claim.

If you have any questions please contact Commercial Grounds Care Inc.
Customer Service Department @ 920-699-2000

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒

WARRANTY ☒

SALES ☐

PARTS ☒



