



One BOB-CAT Lane, P.O. Box 469
 Johnson Creek, WI 53038 U.S.A.
 (920) 699 2000
 Fax: (920) 699 6836

Service Bulletin

Date: 4/20/15

Bulletin No: JC-15-07

Product Type: STEINER 440

Customer Issue:

Breaking shift cables and not shifting properly.

Cause:

Shifter brackets are susceptible to moisture and contaminants getting inside the tube, which can result in binding up and/or shift cable breaking.

Action required:

Order and install shifter pivot kit number **970536** (order from parts dept.)

Products Involved:

Shifter pivots apply to all tractors up to serial number:

- 75720100711
- 75720110331
- 75720120322
- 75720130325

Warranty: This is not a recall. Fix-as-Fails as this will not affect all units.

Regular warranty procedures apply:

1 HR changed 7-2-15

Flat rate is set @ .75hrs of labor for the rear and ~~2hrs~~ of labor for the front mount. For a total of 2.75hrs for kit **970536**.

Please file warranty using (drop-down box) labor code **JC-15-07 Rear and JC-15-07 Front for kit 970536** with one unit per claim.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE

WARRANTY

SALES

PARTS