



Bulletin No: SB2006-02
Category: Steiner
Section: N/A
Index Ref: N/A
Machine/s: 430 Max
Pages: 1
Date: Aug 11, 2006

Type: Service Bulletin

TO: All Steiner Dealers

SUBJECT: 87-046 Couple Assembly and 87-112 Coupler Flange

ISSUE:

Key-way **64164-11** in the **87-046** Coupler Assembly and **87-112** Coupler Flange maybe 1/4" this should be 3/16".

CORRECTION:

Check Coupler Assembly and Coupler Flange key-way dimension. If it is 1/4" it will have to be changed.

PART:

64164-11 Key-way.

AFFECTED SERIAL NUMBERS:

75-70006 serial numbers 75700060335 - 0359.

75-70008 serial numbers 75700080307 – 0321 except 0311, 0314, and 0320.

75-70040 serial numbers 75700400140 – 0143.

WARRANTY:

You may claim up to 1.5 hour of labor and parts for tractors covered under this bulletin. Please file warranty using Service Bulletin number **SB2006-02** with one unit per claim. If you have any question please contact the Jacobsen Customer Support Team at 800-848-1636 options 2,3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒

