



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

SERVICE BULLETIN

Date: April 5, 2012


Bulletin No: JC-006-12

Product Type: 61" FastCat Pro

Issue: Constricted purge/vent line could potentially affect fuel system performance

Cause: Incorrect routing leads to kinking of purge/vent line

Action Required: Remove hose from top of left-hand fuel tank and re-route it under positive battery cable, install new wire ties as illustrated below.




(Enlarged View)

Make Your Move™



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Page 2 of 2



Products Involved: 942406H and 942407H per serial number list attached.

Warranty: You may claim up to .2 hour of labor and parts for units covered under this bulletin. Please select warranty code JC-006-12 from the drop-down labor codes in WarrantySmart™ with one unit per claim.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☐

Make Your Move™