



SERVICE/PARTS BULLETIN

Date: 5-15-2009

Bulletin No: JC-011-09

PRODUCT TYPE: All Fastcat & Rocket Models

ISSUE: Breaking the charge pump cover on the Transaxle.

CORRECTION: To eliminate the purchase of a complete transaxle, we now offer the charge pump kit through our normal parts channel.

PARTS INVOLVED: Kit 4164227 for all units EXCEPT 61" (ZT2800 series Transaxles)
Kit 4164228 for 61" units ONLY (ZT3400 series Transaxles)

See the following page for an illustration of what is included in the kit.

MODELS INVOLVED: All units beginning: 64229xx, 64231xx, 94229xx, 94231xx

WARRANTY: Warranty does not apply.

If you have any questions please contact Schiller Grounds Care, Inc.
Customer Service Department @ 920-699-2000

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☐


SALES

☐

PARTS

☒

ZT 2800 SERVICE SCHEMATIC



Charge Pump Kit -

ZT2800 Transaxle = 4164227 (all except 61" fastcat)

ZT3400 Transaxle = 4164228 (fits 61" FastCat units Only)

ITEMS NOT SHOWN

13 SEALANT
14 OIL, 20W50, 70.3 QZ
200 SEAL KIT
209 HUB PULLER

* - PARTS INCLUDED IN 200 SEAL KIT



P. 1 of 8. 71370-P2