



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

SERVICE BULLETIN

Date: March 1, 2013

Bulletin No: JC-13-11

Product Type: ProCat SE (J models)

Customer Issue: Seat belt bolts could back out.

Cause: Low torque on the seat belt bolts.

Action Required: Torque the two seat belt bolts to the 50-90 ft lb range and no additional Loctite is required.

Products Involved: Serial number range of affected units –

942521J 00600-00614

942522J 00300-00306 and 01200-01226

942523J 00500-00521 and 01200-01201

Warranty: You may claim up to 0.20 hour of labor for units covered under this bulletin. Please file warranty using Service Bulletin Number JC-13-11 with one unit per claim.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☐