

Service Bulletin

Date: June 20, 2013

Bulletin No: JC-13-19

Product Type: Predator, Predator Pro & ProCat G series

Customer Issue: Hydraulic oil leaking on top of the oil tank

Cause: Cap with <u>Cork</u> gasket will deteriorate over time, preventing a good seal.

Action Required: Replace old style oil tank cap (4165236) with new style cap (4167240) that has a rubber seal.



Products Involved:

Model	Ending Serial	Model	Ending Serial		Model	Ending Serial
942500G	94250000652	942508G	94250800174		942515G	94251500290
942501G	94250100242	942509G	94250900071		942516G	94251600188
942502G	94250200609	942510G	94251000073		942517G	94251700149
942504G	94250400795	942511G	94251100106		942518G	94251800131
942505G	94250500265	942512G	94251200135		942519G	94251900111
942506G	94250600202	942513G	94251300106		942520H	94252000132
942507G	94250700139	942514G	94251400477]	942521H	94252100180

Warranty: You may claim up to .1 hour of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number JC-13-19 with one unit per claim.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

