

Jacobsen Information Bulletin

Product Type: Mid-Size Ref. No. N/A Bulletin No: C-036-05

August 8, 2005

Idler Pulley

Product Information

ISSUE:

We have received reports that the bearing in the Idler pulley is not lasting.

CORRECTION:

When replacing 48393 pulley-v idler on the listed models order part number 4135265 pulley-idler in its place.

PARTS INVOLVED:

48393 4135265

INVOLVED PRODUCTS:

732010A, 733010A, 733405A and 733406A

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 2,3,1.

CustomerOne[™] **Product Support**

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

WARRANTY

SALES

PARTS