

# Jacobsen Service Bulletin

Product Type: 4300 TRACTOR

Ref. No. 001

Bulletin No: C-144-03

July 2003

## PTO Belt Length

### Action Required

#### ISSUE:

PTO belt (STEINER 5L420) may be incorrect in length. The incorrect belt will carry the 5L420 part number but not the STEINER logo. The correct belt must carry the STEINER LOGO.

#### CORRECTION:

Install correct PTO belt. The correct belt must carry the STEINER LOGO.

#### EFFECTIVE SERIAL NUMBERS:

73-70005 serial numbers 73700050101 up to and including 73700050111

73-70006 serial numbers 73700060101 up to and including 73700060107

73-70008 serial numbers 73700080101 up to and including 73700080103

#### WARRANTY:

You may claim parts and up to 1 hour of labor for tractors covered under this bulletin. Please file warranty in the normal manner with one tractor per claim.

### CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒

