

April 2001

61" Cutterdecks Anti-Scalp Rollers

Models Affected:

656102

642207, 642223, 642224, 642226

642228, 642230, 642233

Issue

The anti-scalp rollers on the 61" Service Cutterdecks **2720078** have been changed from 3" to 5".

Correction

When replacing a 2720078 Service Cutterdeck with 3" anti-scalp rollers, you will have to order the following additional parts along with the 2720078 Service Cutterdeck.

(7) **2721512** Roller

(7) **2720685** Spacer

(7) **64205-004** Bolt M10x110

(7) **64237-03** Locknut M10

Effective Serial Number

All 656102 Cutterdeck with 3" anti-scalp rollers.

All 642207, 642223, 642224, 642226, 642228, 642230, and 642233 Units with 3" anti-scalp rollers.

Warranty

This is an informational bulletin only. Warranty does not apply.

Parts Involved

2721512 Roller.

2720685 Spacer.

64205-004 Bolt M10x110.

64237-03 Locknut M10

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.