

December 2001

### New Extension Spring

**Models Affected:**  
**930322, 930323, 930324**

#### Issue

We received reports from the field of Hydro Midsize Unit not tracking properly. To correct this we have released a New Hydro Pump Arm Spring (**4117212**) for the Hydro Midsizes.

#### Correction

When ordering a 4113987 Spring, you will receive a **4117212** Spring. Please note that 2 springs are required per unit.

#### Effective Serial Number

93032200060, 00071-00074, and 93032200101 up to and including 93032200396.  
93032300070-00074 and 93032300101 up to and including 93032300386.  
93032400060, 00071-00074, and 93032400101 up to and including 93032400214.

#### Warranty

A warranty claim may be filed for the **4117212** Spring and 0.2 of a hour labor for the repair. Please file warranty in the normal way with only one machine per claim.

#### Parts Involved

4113987 Spring  
4117212 Spring

If you have any questions about this bulletin, please contact the Textron Golf, Turf & Specialty Products Service Department at 920-699-5890.