

Product Type: BZT3310 Ref. No. 009

Bunton Service Bulletin J538

March 2001

Deck Chain Guides

Models Affected: 642300

lssue

We have added Deck Chain Guides **2722267.7** to assist in preventing the lift chains from coming off.

Correction

The Deck Chain Guides **2722267.7** may be added to prior units should they be experiencing problems with the chains coming off. You will need to drill 2) 5/16" holes in front of the front deck lift chains and install the following parts:

2) 2722267.7 Guides
2) 64123-54 Bolts
2) 64163-55 Nuts.

Effective Serial Number

All 642300 units with serial numbers up to and including 64230000236.

<u>Warranty</u>

This is an informational bulletin only. Warranty does not apply.

Parts Involved

2722267.7 Guides. 64123-54 Bolts. 64163-55 Nuts.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.

250-03/01-CU

©Copyright 2001, Textron Inc. All rights reserved Johnson Creek, Wisconsin Printed in the U.S.A.