

March 2001

New Hydro Pumps

Models Affected:

642220, 642221, 642222, 642223
642225, 642226, 642227, 642228, 642233

Issue

A new Hydro Pump **2721615** has been released for the BZT2000's. The pump End Cap and Input Shaft have been changed.

Correction

Please note that when servicing any of the BZT2000 units listed below the following items are different. The hydro pump is now **2721615**, the hoses between the hydro pump and wheel motor is now **2722468** and **2722469**, and the pulley is now **2722382**.

Effective Serial Number

642220 serial numbers 64222000146 and above.
642221 serial numbers 64222100267 and above.
642222 serial numbers 64222200140 and above.
642223 serial numbers 64222300210 and above.
642225 serial numbers 64222500102 and above.
642226 serial numbers 64222600102 and above.
642227 serial numbers 64222700101 and above.
642228 serial numbers 64222800111 and above.
642233 serial numbers 64223300185 and above.

Warranty

This is an informational bulletin only. Warranty does not apply.

Parts Involved

2721615 Hydro Pump.
2722382 Pulley.
2722468 Hose.
2722469 Hose.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.