

December 2001

New Extension Spring

Models Affected:
630322, 630323, 630324

Issue

We received reports from the field of Hydro Midsize Unit not tracking properly. To correct this we have released a New Hydro Pump Arm Spring (**4117212**) for the Hydro Midsizes.

Correction

When ordering a 4113987 Spring, you will receive a **4117212** Spring. Please note that 2 springs are required per unit.

Effective Serial Number

63032200060, 00071, and 63032200101 up to and including 63032200214.
63032300070-00074, and 63032300101 up to and including 63032300225.
63032400060, 00071-00074, 63032400101 up to and including 63032400142.

Warranty

A warranty claim may be filed for the **4117212** Spring and 0.2 of a hour labor for the repair. Please file warranty in the normal way with only one machine per claim.

Parts Involved

4113987 Spring
4117212 Spring

If you have any questions about this bulletin, please contact the Textron Golf, Turf & Specialty Products Service Department at 920-699-5890.