

April 2001

61" Cutterdecks Anti-Scalp Rollers

Models Affected:

956017, 956101, 956102
942206, 942207, 942209, 942223, 942224
942226, 942228, 942230, 942233

Issue

The anti-scalp rollers on the 61" Service Cutterdecks **2186132** have been changed from 3" to 5".

Correction

When replacing a 2186132 Service Cutterdeck with 3" anti-scalp rollers, you will have to order the following additional parts along with the 2186132 Service Cutterdeck.

- (7) **2721512** Roller
- (7) **2720685** Spacer
- (7) **64205-004** Bolt M10x110
- (7) **64237-03** Locknut M10

Effective Serial Number

All 956017, 956101, and 956102 Cutterdecks with 3" anti-scalp rollers.

All 942206, 942207, 942209, 942223, 942224, 942226, 942228, 942230, and 942233 Units with 3" anti-scalp rollers.

Warranty

This is an informational bulletin only. Warranty does not apply.

Parts Involved

- 2721512 Roller.
- 2720685 Spacer.
- 64205-004 Bolt M10x110.
- 64237-03 Locknut M10

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.