

March 2001

New Hydro Pumps

Models Affected:

**942211, 942220, 942221, 942222, 942223
942224, 942225, 942226, 942227, 942228**

Issue

A new Hydro Pump **2721615** has been released for the ZT200's. The pump End Cap and Input Shaft have been changed.

Correction

Please note that when servicing any of the ZT200 units listed below the following items are different. The hydro pump is now **2721615**, the hoses between the hydro pump and wheel motor is now **2722468** and **2722469**, and the pulley is now **2722382**.

Effective Serial Number

942211 serial numbers 94221100600 and above.
942220 serial numbers 94222000210 and above.
942221 serial numbers 94222100480 and above.
942222 serial numbers 94222200177 and above.
942223 serial numbers 94222300534 and above.
942224 serial numbers 94222400337 and above.
942225 serial numbers 94222500121 and above.
942226 serial numbers 94222600139 and above.
942227 serial numbers 94222700122 and above.
942228 serial numbers 94222800113 and above.

Warranty

This is an informational bulletin only. Warranty does not apply.

Parts Involved

2721615 Hydro Pump.
2722382 Pulley.
2722468 Hose.
2722469 Hose.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.