





Bobcat/Bunton Information Bulletin

Product Type: LEO/ ESTATE PRO

Ref. No.

Bulletin No: C-160-03

October 2003

Exhaust Smoke On 17.5HP ZTR

Product Information

ISSUE:

We have received reports of smoke coming from engine exhaust on models LEO 942280 and ESTATE PRO 642280 while operated under high load on uneven terrain. We have identified two conditions that contribute to this problem:

- 1) The choke may not be fully open during operation.
- 2) The oil level in the crankcase may be too high for this operating condition.

CORRECTION:

The color of the smoke will indicate whether the problem is choke related or oil related. Use the following procedures after determining the source of the problem.

If black smoke:

- 1) Inspect air intake system for restrictions; clean or replace the air filter.
- 2) Inspect sparkplug for fouling; replace if required.
- 3) Inspect choke for proper operation; adjust so plate is completely open when choke is off.
- 4) Ensure the governor lever does not bump against the choke link under full throttle settings.

If blue or white smoke:

- 1) Check oil level on dipstick.
- If oil is above full mark on dipstick, drain excess oil down to full mark, then re-test unit. This may resolve many complaints on units operated under borderline terrain conditions.
- 3) If problem persists, order from an authorized Briggs and Stratton Dealer and install dipstick p/n **699908**, which provides for a slightly lower oil level at the full mark. This is a safe oil level for the engine and should resolve any remaining complaints for those units operated under the conditions noted above.









Χ

Page2 Bulletin C-160-03

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:

LEO: All 942280 serial numbers ESTATE PRO: All 642280 serial numbers

WARRANTY:

This bulletin is for information purposes only. If you have any questions, please contact your Briggs & Stratton Central Sales and Service Distributor and refer to Central Bulletin #2003-6.

CustomerOne[™] Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE **X** WARRANTY **X** SALES PARTS

