

June 1999

### New Pump Belt

**ZT100 Models Affected:  
942102, 942103, 942104, 942105**

#### **Issue**

We have received reports that some **2228049** pump belts have been failing prematurely.

#### **Correction**

When ordering a replacement belt **2228049**, you will receive a belt with a different cord construction. The new belt can be identified by a yellow stripe across the belt near the part number.

#### **Effective Serial Number**

All 942102.

All 942103.

All 942104.

All 942105.

#### **Warranty**

This bulletin is for informational purposes only.

#### **Attachments**

None.

If you have any questions about this bulletin, please contact the Textron Turf Care and Specialty Products Service Department at 920-699-2000.