

Product Type: ZT100

Bob-Cat

Ref. No. 006 Service Bulletin 426

July 1999

Grass Box Latch Rod

ZT100 Models Affected: 942102, 942103, 942104, 942105

<u>Issue</u>

A new Grass Box Latch Rod 2720339 has been released to allow for clearance when installing the ROPS 970147.

Correction

When installing the ROPS **970147** replace the Grass Box Latch Rod **2228078** with the new Grass Box Latch Rod **2720339**.

Effective Serial Number

All 942102.

All 942103.

All 942104.

All 942105.

Warranty

The new Grass Box Latch Rod 2720339 can be claimed for .

Attachments

None

If you have any questions about this bulletin, please contact the Textron Turf Care and Specialty Products Service Department at 920-699-2000.