



B u n t o n

Product Type: BZT3310 Ref. No. 002

Service Bulletin J453_{Rev01}

May 2000

New Control Arm Dampner

Models Affected:
642300

Issue

A new stiffer steering Control Arm Dampner has been released for the BZT3310.

Correction

When ordering a new Dampner, please order **2721172**. The new dampner will have a white spot on the end to identify it.

Please note that the old Dampner will not automatically supercede to the new Dampner.

Effective Serial Number

All 642300 power units.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2721172 Control Dampner.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty products Service Department at 920-699-5890.