



Product Type: BZT1000 Ref. No. 006

# Bunt on

## Service Bulletin J461

---

---

May 2000

### New Caster Wheels and Hubs

**BZT1000 Models Affected:  
654204, 654803, 654804**

#### **Issue**

Commonality of parts across several product lines.

#### **Correction**

When ordering Rims 38506 or 38507 you will receive (1) **2720644** and (1) **2720645** Rim Halves.

When ordering Wheel 38510 you will receive **2720646** Wheel.

When ordering Filled Wheel 38510-01 you receive **2720656** Filled Wheel.

It is recommended that when replacing any of these components you replace both sides to prevent uneven heights of cut.

#### **Effective Serial Number**

All 654204, 654803, and 654804 cutterdecks.

#### **Warranty**

This bulletin is for informational purposes only. Warranty does not apply.

#### **Parts Involved**

2720644 Rim Half.

2720645 Rim Half.

2720646 Wheel.

2720656 Filled Wheel.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.