

May 2000

New Caster Wheels and Hubs

ZT100 Models Affected:
954203, 954204, 954803, 954804

Issue

Commonality of parts across several product lines.

Correction

When ordering Rims 38506 or 38507 you will receive (1) **2720644** and (1) **2720645** Rim Halves.

When ordering Wheel 38510 you will receive **2720646** Wheel.

When ordering Filled Wheel 38510-01 you receive **2720656** Filled Wheel.

It is recommended that when replacing any of these components you replace both sides to prevent uneven heights of cut.

Effective Serial Number

All 954203, 954204, 954803, and 954804 cutterdecks.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2720644 Rim Half.

2720645 Rim Half.

2720646 Wheel.

2720656 Filled Wheel.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.