

Product Type: BZT1000 Ref. No. 007



May 2000

New Clutch

Models Affected: 642104 & 642105

Issue

A new clutch has been released for the BZT1000's. This clutch will now have a serviceable harness between the clutch and main harness.

Correction

When replacing a 2188151 Clutch you will receive (1) 2721338.7 Bracket, (1) 2721337 Clutch, and (1) 38304-03 Bushing.

When ordering a 2186212.7 Bracket you will receive a 2721338.7 Bracket.

Effective Serial Number

All 642104 and 642105

Warranty This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2721338.7 Bracket. 2721337 Clutch. 38304-03 Bushing.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.

©Copyright 2000, Textron Inc. All rights reserved Johnson Creek, Wisconsin Printed in the U.S.A.