



Product Type: BZT3310 Ref. No. 003

Bunt on

Service Bulletin J471

May 2000

New Clutch

Models Affected: 642300

Issue

A new clutch has been released for the BZT3310's. This clutch will now have a serviceable harness between the clutch and main harness.

Correction

When replacing a 2188151 Clutch you will receive (1) **2721338.7** Bracket, (1) **2721337** Clutch, and (1) **38304-03** Bushing.

When ordering a 2186212.7 Bracket you will receive a **2721338.7** Bracket.

Effective Serial Number

All 642300.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2721338.7 Bracket.
2721337 Clutch.
38304-03 Bushing.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.