

Product Type: ZT331 Ref. No. 004

# **Bob-Cat** Service Bulletin J474

May 2000

## **Caster Supports**

### Models Affected: 942300

#### Issue

We have received reports from the field that under certain applications the Caster Support Arms **2256002.7** and **2256003.7** may be cracking.

#### **Correction**

If your Caster Support Arms are cracking around the mounting holes please order the following parts:

(1) **2256002.7** Caster Support RH, (1) **2256003.7** Caster Support LH, (4) **64123-24** Bolts, (4) **64229-05** Nuts, and (8) **64163-67** Washers.

#### Effective Serial Number

All 942300 units.

#### **Warranty**

Please file warranty in the normal way with only one unit per claim. You may claim for parts and up to 15 mins labor ( each side ) for units in the normal warranty period.

#### Parts Involved

2256002.7 Caster Support RH. 2256003.7 Caster Support LH. 64123-24 Bolts. 64229-05 Nuts. 64163-67 Washers.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.

250-05/00-CU