



Product Type: Midsize Ref. No. 005

Bob-Cat

Service Bulletin J476

July 2000

Removal of Variable Speed Clutch Rod and PTO Belt

Models Affected:
933400, 934400, 935400

Issue

We have removed the Variable Speed Clutch Rod and PTO Belt from the above mentioned Cutterdecks.

Correction

When ordering any of the above mentioned Cutterdecks to be used on a Variable Speed Unit please follow the information below.

933400 use (1) **33257-03** Rod and (1) **38470** Belt.

934400 use (1) **33247-03** Rod and (1) **38439** Belt.

935400 use (1) **33247-02** Rod and (1) **38291** Belt.

Effective Serial Number

All 933400, 934400 & 935400 Cutterdecks.

Warranty

This is for informational purposes only. Warranty does not apply.

Parts Involved

33257-03 Rod.

33247-03 Rod.

33247-02 Rod.

38470 Belt.

38439 Belt.

38291 Belt.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.