

August 2000

### Caster Wheel Bearing Update

**Models Affected:**  
**955202, 956102**

#### **Issue**

If your Caster Yoke 2186123 is still serviceable, it is not necessary to change the complete caster assembly. Please note the instructions below when ordering replacement parts.

#### **Correction**

You may service the **2188123** Wheel Hub as follows:

Order (1) **2720475** Wheel Hub and (1) **2720474** Spacer.

Install the new spacer in the new wheel hub then slide the old spacer into the new spacer. It may be necessary to grind the ends of the old spacer as we just want it to act as a guide and float in the new spacer. Install the wheel and hub assembly back into the caster yoke and tighten the bolt.

#### **Effective Serial Number**

All 955202 and 956102 decks.

#### **Warranty**

This bulletin is for informational purposes only. Warranty does not apply.

#### **Parts Involved**

2188123 Wheel Hub.

2720474 Spacer.

2720475 Wheel Hub.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.