



Product Type: BZT2000 Ref. No. 010

Bunt on

Service Bulletin J489

August 2000

Caster Wheel Bearing Update

Models Affected:
655202, 656102

Issue

If your Caster Yoke 2186123 is still serviceable, it is not necessary to change the complete caster assembly. Please note the instructions below when ordering replacement parts.

Correction

You may service the **2188123** Wheel Hub as follows:

Order (1) **2720475** Wheel Hub and (1) **2720474** Spacer.

Install the new spacer in the new wheel hub then slide the old spacer into the new spacer. It may be necessary to grind the ends of the old spacer as we just want it to act as a guide and float in the new spacer. Install the wheel and hub assembly back into the caster yoke and tighten the bolt.

Effective Serial Number

All 655202 and 656102 decks.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2188123 Wheel Hub.

2720474 Spacer.

2720475 Wheel Hub.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.