

Product Type: BZT2000 Ref. No. 012

Bunton Service Bulletin J501

October 2000

New Deck Cradle

Models Affected: 642201, 642203, 642204, 642206, 642207 642213, 642215

Issue

We have released a New Deck Cradle **2721076.7** for all the BZT2000 units.

Correction

When replacing the Deck Cradles on the above listed Power Units please order the following, Deck Cradle **2721076.7**, (2) **2721644.7** Lift Plates, and a **2721645.7** Mounting Bracket.

Effective Serial Number

All 642213 and 642215 units.

All **642201** units with serial numbers up to and including 64220100318 will require you to order the new style cradle and hardware when replacing the original cradle.

All **642203** units with serial numbers up to and including 64220300473 will require you to order the new style cradle and hardware when replacing the original cradle.

All **642204** units with serial numbers up to and including 64220400211 will require you to order the new style cradle and hardware when replacing the original cradle.

All **642206** units with serial numbers up to and including 642206008315 will require you to order the new style cradle and hardware when replacing the original cradle.

All **642207** units with serial numbers up to and including 64220700366 will require you to order the new style cradle and hardware when replacing the original cradle.

Warranty This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2721076.7 Cradle. 2721644.7 Lift Plate. 2721645.7 Mounting Bracket.

If you have any questions about this bulletin, please contact the Textron Golf, Turf & Specialty Products Service Department at 920-699-5890.