

Product Type: BZT3310

Ref. No. 008

Bunton Service Bulletin J514

December 2000

New Suspension Seat

Models Affected: 642300

Issue

We have replaced the seat on the BZT3310 with a New Suspension Seat **970190**.

Correction

When ordering a 1985025 seat you will receive a **970190** Seat Kit. Please see the drawing in this bulletin as you will have to drill new mounting holes. Service parts for the 1985025 set will still be available.

Effective Serial Number


All 642300 units.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

1985025 Seat. 970190 Seat Kit.



If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.