

Product Type: Aerator

Ref. No. 001

Product Informational Bulletin J608

February 2003

Honda Engine Speed

Models Affected: All Lawnaire IV and V's with Honda Engines

Issue

It has been brought to our attention that the Lawnaire IV and V's may have the maximum engine speed set to high.

Correction

If you presently own a Lawnaire unit with a Honda Engine please check that the maximum engine rpm is set to 3200 rpm's.

Effective Serial Number

All Lawnaire IV and V's with Honda Engines.

Warranty

This is an informational bulletin and warranty does not apply.

Parts Involved

547728 - Honda Engine

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.