





Bobcat/Bunton Information Bulletin

Product Type: ZT2 Series/ BZT2 Series Ref. No. 001

BulletinNo: C-007-04

February 1, 2004

ZT DIESEL ENGINE OIL FILL AND DRAIN TUBE

Product Information

ISSUE:

There have been reports from the field of the engine oil fill and drain tube cap is not staying seated in the tube.

CORRECTION:

During daily maintenance and periodical observation, attention needs to be made to make sure that the cap is secured in the oil fill and drain tube.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models: 64222500070-71, 101-108 64222600070-78, 101-115 94220800070-71, 101-104 94220900071, 73-74, 101-137 94222500101-119 94222600070, 101-165

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

CustomerOne[™] Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE	X	WARRANTY	SALES	PARTS X	
	^				

