

Bobcat/Bunton Information Bulletin

Product Type: Mid-Size

Ref. No. 001

Bulletin No: C-004-04

January 26, 2004

Brake Drum

Product Information

ISSUE:

Release of new Brake Drum to help reduce brake squeal.

CORRECTION:

When replacing the Brake Drum you will need to order quantity (1) of part number 4124853 Drum-Brake and quantity (4) of part number 64197-021 Bolt for each side.

PARTS INVOLVED:

4124853 Drum-Brake	Quantity 1
64197-021 Bolt	Quantity 4

INVOLVED PRODUCTS:

Bobcat Models: 930022, 930023, 930024, 932010, 933010, 934010, 930022A, 930023A, 930024A, 932010A, 933010A, 934010A.

Serial Numbers: All

Bunton Models: 634010, 633010, 630022, 630023, 633010A, 634010A.

Serial Numbers: All

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE	<input checked="" type="checkbox"/>	WARRANTY	<input type="checkbox"/>	SALES	<input type="checkbox"/>	PARTS	<input checked="" type="checkbox"/>
---------	-------------------------------------	----------	--------------------------	-------	--------------------------	-------	-------------------------------------