



Bobcat/Bunton Service Bulletin

Product Type: LEO/ESTATE PRO

Ref. No. N/A

Bulletin No: C-020-04

July 22, 2004

970314 KIT- TRAC CTRL LEVER

Action Required

ISSUE:

We have received complaints from the field that some units may have weak transaxles. In most cases this is correct by installing the **970314 KIT- TRAC CTRL LEVER**.

For warranty consideration of any transaxles this kit must first be installed.

CORRECTION:

Install **970314 KIT- TRAC CTRL LEVER**.

PARTS INVOLVED:

970314 KIT-TRAC CTRL LEVER.

INVOLVED PRODUCTS:

642280 serial numbers 64228000101 up to and including 64228000171
642281 serial numbers 64228100101 up to and including 64228100308
642282 serial numbers 64228200101 up to and including 64228200137
942280 serial numbers 94228000070 up to and including 94228000401
942281 serial numbers 94228100070 up to and including 94228100768
942282 serial numbers 94228200070 up to and including 94228200299

WARRANTY:

You may claim parts and up to 1.5 hours labor allowed for units covered under this bulletin. Please file warranty, using **Campaign Number C-020-04**, with one unit per claim. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒

