

Bobcat/Bunton Service Bulletin

Product Type: ZT

Ref. No. N/A

Bulletin No: C-023-04

June 21, 2004

ZT DIESEL ENGINE OIL FILL AND DRAIN TUBE

Action Required

ISSUE:

There have been reports from the field of the engine oil fill and drain tube cap is not staying seated in the tube.

CORRECTION:

Order the parts listed in Parts Involved, from your Yanmar Industrial Engine Distributor and install them on the affected units listed. If you need help finding your Yanmar Industrial Engine Distributor please contact Yanmar Diesel America Corp. at 1-847-541-1900 and they will assist in locating your Distributor.

PARTS INVOLVED:

<u>Yanmar Part No.</u>	<u>Description</u>	<u>Quantity</u>
118400-34800	Dipstick guide assembly	1
118200-49120	Bend guide gasket	1
26106-060202	Bolt	2
118400-01750	Filler cap	1
118400-01760	Filler cap gasket	1

INVOLVED PRODUCTS:

642225 serial numbers 64222500070, 0071, 0101 up to and including 0108.
642226 serial numbers 64222600070 – 0078, 0101 up to and including 0115.
942208 serial numbers 94220800070, 0071, 0101 up to and including 0104.
942209 serial numbers 94220900071 – 0074, 0101 up to and including 0137.
942225 serial numbers 94222500101 up to and including 0119.
942226 serial number 94222600070, 0101 up to and including 0165.
942236 serial numbers 94223600071 – 0075, 0101 up to and including 0135.

WARRANTY:

You may claim parts (include a copy the invoice) and up to 1.0 hour labor allowed for units covered under this bulletin. Please file warranty, using **Factory Approval Number C-023-04**, with one unit per claim. If you have any questions please contact the Johnson Creek Customer Service team at 1-800-848-1636 option 2,2.

All repairs must be completed by December 1, 2004. No warranty claims for this repair will be processed after January 1, 2005.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒