



Zero Turning Mower

Model ZTMD52

Starting Serial No. 1001

Illustrated Parts List for Mower Deck Only



CAUTION

Avoid injuries. Read and understand Operator's manual
before operating unit or equipment.
It contains instructions for safe operation.



CAUTION

- READ AND UNDERSTAND OPERATORS MANUAL BEFORE OPERATING OR SERVICING.
- OBEY ALL SAFETY INSTRUCTIONS. FAILURE TO DO SO MAY RESULT IN INJURY TO YOU OR OTHERS.
- BE SURE MACHINE IS IN SAFE OPERATING CONDITION BEFORE USE.
- INSPECT MACHINE DAILY. REPLACE ALL WORN OR DAMAGED PARTS.
- KEEP ALL GUARDS AND SHIELDS IN PLACE.
- CHECK OPERATION OF ALL SAFETY INTERLOCK SWITCHES DAILY.
- DO NOT OVERRIDE INTERLOCK SYSTEM, IT IS FOR YOUR PROTECTION.
- DO NOT ALLOW MINORS OR THE INEXPERIENCED TO OPERATE MACHINE.
- KEEP PEOPLE AND PETS A SAFE DISTANCE AWAY FROM MACHINE USING POWER DRIVEN ATTACHMENTS. INJURY COULD RESULT FROM FLYING DEBRIS.

Date of Purchase: Month _____ Day _____ Year _____

Dealer Name _____ Phone _____

Serial Number _____

Model Number _____

ALWAYS GIVE MODEL AND SERIAL NUMBER WHEN ORDERING SERVICE PARTS

STEINER
TEXTRON

Steiner Division of Textron Inc.


STEINER TURF EQUIPMENT, INC.
289 N. Kurzen Rd., P.O. Box 504
Dalton, Ohio 44618

Telephone: (330) 828-0200
FAX: (330) 828-1008

TABLE OF CONTENTS

Deck Parts	Section 1	page
Mower Deck Parts	Fig. 1	1-2
Drive Parts & Belts.....	Fig. 2.....	1-4
Spindle Parts	Fig. 2A	1-6
 Decals	 Section 2	
Decals.....	Fig. 3.....	2-1

**Mower Deck Parts
Figure 1**





Parts List for Figure 1

Ref.	Part No.	Description	Quantity
1	6111020 (REF)	Frame Weldment (See ZTM325 Parts Manual)	
2	6112046	Arm, Deck Mounting	4
3	29-010	Grease Fitting, 1/4 Short	4
4	03-1222	Clevis Pin, 3/4 X 2-3/4	4
5	03-024	Snap Pin	4
6	99-E13	Flange Nut, 3/8	16
7	6112055	Deck Mounting Bracket, R.H.	1
8	6112052	Deck Mounting Bracket, L.H.	1
9	6112058	Pulley Cover, L.H.	1
*	6112059	Pulley Cover, R.H.	1
	56-002	Flexthead, Anti-Slip 6" Wide	1.5 ft.
10	99-K11	Bolt, Flange 3/8 X 3/4	8
11	6112079	52" Cutting Deck Weldment	1
12	6112041	Deck Bracket	2
13	6112038	Chute Deflector Weldment	1
14	41-085	Spring, Torsion	1
15	6112045	Shaft, Chute Deflector	1
16	02-RP0612	Roll Pin, 3/16 X 1-1/2	1
17	90-0836	Bolt, 1/2 X 4-1/2	4
18	99-K13	Bolt, Flange 3/8 X 1	8
19	99-B59	Washer, Machine 1/2 ID 18 GA	4
20	06-051	Roller, Rear Anti-Scalp	1
21	6112044	Axle, Roller	1
22	02-CP0306	Cotter Pin, 3/32 X 3/4	2
23	95-08	Flat Washer, 1/2 SAE	32 or AR
24	06-050	Roller, Plastic Anti-Scalp	4
25	99-E41	Locknut, Nylon 1/2	4
26	6111230	Roller Chain, Deck Rear (See ZTM325 Mower Parts Manual)	2
27	81-056	Connector Link, #40 (See ZTM325 Mower Parts Manual)	3
28	6111016	Stud, Deck Lift (See ZTM325 Mower Parts Manual)	3
29	F4002	Jam Nut, 7/16 UNC	3
30	03-0820	Clevis Pin, 1/2 x 2-1/2	3
31	02-CP0406	Cotter Pin, 1/8 x 3/4	3
32	99-K19	Bolt, Flange 5/16 x 3/4	9
33	6112074	Bracket, Deck Lift	3
34	99-E12	Flange Nut, 5/16	9
35	41-090	Spring, Torsion 5/8 OD	3
36	6112075	Spacer	3
37	99-E48	Flange Nut, 7/16	3
38	6111229	Roller Chain, Deck Front (See ZTM325 Mower Parts Manual)	1
39	94-06	Flat Washer, 3/8 USS	8

* Not Illustrated


Drive Parts & Belts
Figure 2



Parts List for Figure 2

Ref.	Part No.	Description	Quantity
1	6112079 (REF)	52" Cutting Deck Weldment (See Fig. 1, Ref. 11)	
2	83-H16SPL	Bushing, H X 1" Split Type	3
3	96-04	Lock Washer, 1/4	6
4	90-0406	Bolt, 1/4 X 3/4	6
5	29-045	Grease Fitting, 1/4 45 Degrees	2
6	85-K0408	Key, 1/4 X 1	3
7	29-010	Grease Fitting, 1/4 Short	1
8	6112076	Sheave, 2-Groove BK45/BK47	1
9	83-BK45H	Sheave, BK45 H-Bushing	2
10	90-1014	Bolt, 5/8 X 1-3/4	1
11	6112069	Deck Idler Weldment	1
12	41-086	Spring, Tension 5-3/4" Length	1
13	03-022	Clip, Peg Board Hook	1
14	95-08	Flat Washer, 1/2 SAE	1
15	99-B58	Washer, Machine 5/8 ID 14 GA	6
16	29-122	Grease Fitting, 1/4-28 45 Degrees (long)	1
17	83-045	Pulley, Flat Idler 4.12" OD	1
18	99-G10	Shakeproof Washer, 5/8"	1
19	92-10	Nut, 5/8	1
20	F3013	Nut, Stover Flange 3/8	1
21	94-06	Flat Washer, 3/8 USS	1
22	99-E13	Flange Nut, 3/8	12
23	87-143	Spindle, Mower 1/2 RH Threads	3
24	99-K22	Bolt, Flange 3/8 X 1-1/4	12
25	79-126	Blade, 18" Hi-Lift 1/2" Hole	3
	79-127	Blade, 18" Lo-Lift 1/2" Hole (Optional)	3
26	99-B14	Washer, 1/4 X 1/2 ID X 3 OD	3
27	91-0810	Bolt, 1/2 X 1-1/4 NF	3
28	81-092	Belt, 100.5"	1
29	81-091	Belt, 123" (Kohler)	1
	81-095	Belt, 134.9" (Kawasaki)	1

Spindle Parts
Figure 2A



Parts List for Figure 2A

Ref.	Part No.	Description	Quantity
1	87-235	Shaft, Spindle	1
2	87-209843	Seal	2
3	87-244643	Bearing Cone	2
4	87-244610	Bearing Cup	2
5	87-240001-5	Casting, w/o breather hole	1
	87-240001-6	Casting, with breather hole	1
7	87-203293	Retaining Ring	2
8	87-203815	Bolt, 3/8 x 1-1/2 SHCS	4
9	87-240101-01	Blade Adapter with Cup	1

Decals
Figure 3



Parts List for Figure 3

Ref.	Part No.	Description	Quantity
1	00-092	Decal, Keep Hands and Feet	3
2	00-093	Decal, Warning Read Owner's Manual	1
3	00-139	Decal, Warning Discharge Chute	2
4	00-209	Decal, Made in the U.S.A.	1

